



Note 1: These features to be removed from landfill area prior to completion of soil remedy.
Site Plan created from Arcadis CAD drawings received December 2015.
Aerial imagery accessed via ArcGIS Online and provided by the United States Department of Agriculture on 2 May 2018.
Image is dated 31 July 2015.

Legend

●

Areas of Particular Concern
(to be capped or excavated) (7)

■

Potential Source Area to be Removed (1)

—

Areas Determined to be Mostly
Non-Vegetated During Field
Inspection

Edge of landfilled wastes (dashed where
approximate)

Great Swamp National Wildlife Refuge
property boundary

▨

Areas where surface water flow does not
exhibit typical bed and bank morphology

▨

Waste and debris observed on ground
surface but not observed or anticipated
below ground surface

■

Open water

400 200 0 400 Feet

Location of APCs and
Mostly Non-Vegetated Areas

ROLLING KNOLLS LANDFILL SUPERFUND SITE
CHATHAM, NEW JERSEY

Geosyntec
consultants

Princeton, NJ May 2018

Figure
5-1

ED_004977_00001258-00001